

# CCM Technical Maintenance Bulletin



Bulletin 21 - November 14, 2012

## Reporting of Errors

Your help can improve this bulletin. If you find mistakes or you know of a way to improve the procedures, please let us know at [mnr@ccmpool.com](mailto:mnr@ccmpool.com)



All CCM repair vendors are required to comply with Safety & Security Regulations imposed by Terminal Operators where work is performed, in accordance with the License Agreement and Article 5.8 of the Form Agreement D.

## Are you registered with DRS?

All truckers and depots are encouraged to register no later than June 1, 2010. For details visit us at [www.chassis.com](http://www.chassis.com)



## This bulletin approved by:

James Reo  
Director of Maintenance  
320 Croft Crossing  
Chesapeake, VA 23320

Phone: 757-613-2893  
Fax: 757-842-6897  
E-mail: [jreo@ccmpool.com](mailto:jreo@ccmpool.com)

## Securement of Light Assemblies

### Summary

Recently we have noted an increase in the amount of lights being stolen from CCM maintained equipment. With this in mind we feel that it is appropriate to reexamine the installation of lights

Please note that Section 10 of the CCM M&R Procedure Manual V3.0, states *"All lights are to be replaced with...flange mounted sealed beam lights..."* and that *"Flange mounted lights must have a minimum of three fasteners"...* Fasteners should be **steel** rivets, though in some cases (when approved by the Pool Manager) screws will be allowed."

Please note that we have previously allowed the use of steel shank drive rivets in this application. Recent research indicates that these rivets are not a deterrent to theft.

For this reason, please note that all light replacements must be made using stainless steel pop rivets only. Aluminum pop rivets and drive rivets of any kind are no longer acceptable means of attachment.

Please note also that we have checked with the parts suppliers and have been assured that the present amount built into the system for rivets is sufficient to cover the cost of stainless steel pop rivets. Therefore there will not be an adjustment in the price of lights in response to this change.

Please direct any questions or comments on this matter to the CCM Maintenance Department.