



Technical Bulletin

No. 30

Published: 3 February 2014

Topic: CCM Brake Replacement Program – DCLI Equipment

As you know, DCLI has always requested the use of B-Lock brakes shoes on their equipment to reduce the incidents of rust jacking.

In an effort to address DCLI's desire to maintain their equipment with a brake shoe that controls rust jacking and control the costs for all parties, CCM is changing its brake replacement program. It is the purpose of this document to detail the change to the brake program.

Instead of B-Lock shoes CCM has agreed to provide DCLI with **Arvin Meritor OEM Platinum Plus** brake shoes with **MA212** friction lining. The **OEM Meritor Platinum Plus** shoe is now the only shoe approved for installation on **all DCLI** Equipment managed by CCM equipment in all pools effective **1 December 2013**.

CCM has negotiated a price for these shoes with several national suppliers. Martec, New Life and Genuine Parts Company should all be able to provide the following parts at the point to allow the vendors to charge the prices indicated below

<u>Description</u>	<u>Part Code</u>	<u>Part</u>	<u>MFG</u>	<u>Price</u>
Meritor Platinum Plus OEM brake shoes MA212 - 4515	PSMA2124515	PSMA2124515Q	Meritor	\$23.63
Meritor Platinum Plus OEM brake shoes MA212 - 4707	PSMA2124707	PSMA2124707Q	Meritor	\$23.63
Meritor Brake Hardware kit - HD	4515QHDB	MKT4515QHDB	Meritor	\$6.39
Brake kit with New Shoes with Parts Kit-2 shoes, 2lbs grease, hubcap gasket	BkKtw/oBrg	Brake Kit 2	Meritor	\$61.96

Please ensure that all repair vendors and M&R Surveyors are advised of this change as soon as possible.

Please direct all questions and/or comments on this matter to the M&R Technical Services Manager