

Technical Bulletin

No. 44

Published: 26 May, 2015

Topic: Replacement of Incandescent Surface Mount Lights

Surface mount lights are highly prone to damage due to their high profile. To reduce the likelihood of damage to these lights CCM has made the decision to convert all surface mount Marker lights to a lower profile LED light. To accommodate this conversion CCM would like to use the Peterson 215 series light for all occasions where there is any damage to a surface mount incandescent light. This includes the replacement of either bulbs or lens to a surface mount incandescent light.



Please note that the Peterson 215 looks like a 2 ½ inch rectangular reflector (available in either red or amber) and contains a single LED light in a self-grounding enclosure. It has a height of less than 1.0 inch. Since this light also contains a reflector it will also eliminate the need for an adjacent reflector.

Please direct any further questions on this matter to the CCM Chassis Technical Department